



**HAL**  
open science

## Corrosion initiation and propagation of RC beams cracked by loading under chloride environment

Linwen Yu, Raoul François, Vu Hiep Dang, V. L'Hostis, R. Gagné

► **To cite this version:**

Linwen Yu, Raoul François, Vu Hiep Dang, V. L'Hostis, R. Gagné. Corrosion initiation and propagation of RC beams cracked by loading under chloride environment. CIGOS 2015 - Conférence Internationale: Constructions Innovantes / CIGOS 2015: Innovations in Construction, Mar 2015, Cachan, France. cea-02509080

**HAL Id: cea-02509080**

**<https://cea.hal.science/cea-02509080>**

Submitted on 16 Mar 2020

**HAL** is a multi-disciplinary open access archive for the deposit and dissemination of scientific research documents, whether they are published or not. The documents may come from teaching and research institutions in France or abroad, or from public or private research centers.

L'archive ouverte pluridisciplinaire **HAL**, est destinée au dépôt et à la diffusion de documents scientifiques de niveau recherche, publiés ou non, émanant des établissements d'enseignement et de recherche français ou étrangers, des laboratoires publics ou privés.

# Corrosion initiation and propagation of RC beams cracked by loading under chloride environment

## **Linwen Yu**

Université de Toulouse, UPS, INSA; LMDC, Toulouse ; Université de Sherbrooke, Québec, Canada (liyu@insa-toulouse.fr)

## **Raoul François**

Université de Toulouse, UPS, INSA; LMDC, Toulouse (raoul.francois@insa-toulouse.fr)

## **Vu Hiep Dang**

Hanoi Architectural University, Department of Civil Engineering, Hanoi, Vietnam (dangvuhiep2009@yahoo.com)

## **Valérie L'Hostis**

CEA Saclay, CEA, DEN, DPC, SECR, Laboratoire d'Etude du Comportement des Bétons et des Argiles, Gif-sur-Yvette, France (Valerie.lhostis@cea.fr)

## **Richard Gagné**

Université de Sherbrooke, Québec, Canada (richard.gagne@usherbrooke.ca)

## **Abstract:**

This paper deals with corrosion initiation and propagation in pre-cracked reinforced concrete beams exposed to a chloride environment under sustained loading. The cracking maps, corrosion maps, chloride profiles, cross-section loss and corrosion rate of one group of two beams cast in 2010 were examined. Experimental results show that, after rapid initiation of corrosion at the crack tip, the corrosion process almost stops and the time elapsing before corrosion re-start depends on the exposure conditions and also on the cover depth. The case of horizontal tensioned (and cracked) surface exposed to chloride appears to be very detrimental condition leading to fast propagation stage of corrosion and high corrosion rate.

**Key words:** corrosion initiation; corrosion propagation, chloride; cracks, reinforcement